



furniture works



Inspection Report

Shippers Order #: **1234567**

Prepared For: **Your Moving Company
1234 Moving Way
Anytown, State 98765
Attn: Company Rep
inspections@movingcompay.biz
Phone: (800) 123-4567 Ex. 123**

Concerning: **Mr. A. Shipper
4321 Broken Dr.
Corpus Christi, TX 78413
(361) 723-0196
-
-**

Date Received: **Feb. 12, 2010**

Date Prepared: **Feb. 23, 2010**

In this report, the inspector will note which items were Inspected (I), Not Inspected (NI) or Not Present (NP). It will also be noted whether the damaged items are a result of Moving Damage (MD) or Pre-Existing Damage (PED) based on the judgement of the inspector. Comments may be provided by the inspector concerning the damage witnessed and repair cost if the item is deemed repairable.

Prepared By: **CC Furniture Works
4201 Belfast Drive
Corpus Christi, TX 78413
361-723-0196 * 361-814-2796 fax
movingclaims@ccfurnitureworks.com
www.ccfurnitureworks.com**



Additional Information Provided By Inspector

I = Inspected
NP = Not Present

NI = Not Inspected

MD = Moving Damage
PED = Pre Existing Damage

I NI NP

MD PED

Item # 307

Item Description: Floor lamp

Damage Description

Base is cracked at the pole and the pole is bent and loose at each joint. Not repairable.

Est. Replacement Cost
\$50.00

Est. Repair Cost
N/A



I NI NP

MD PED

Item # 248

Item Description: Coffee table

Damage Description

Metal legs are bent due to heavy items being stacked on table during shipping. Legs can be bent back and black finish touched up at the repair to match the other items in the living room set.

Est. Replacement Cost
\$300.00

\$ -

Est. Repair Cost
\$50.00



I = Inspected
NP = Not Present

NI = Not Inspected

MD = Moving Damage
PED = Pre Existing Damage

I NI NP

MD PED

Item # 250

Item Description: Decorative storage chest

Damage Description

Lid to the chest is broken off at the hinges. The hinges are still attached to the base and the lid can be repaired and reattached.

Est. Replacement Cost

\$80.00

Est. Repair Cost

\$45.00



I NI NP

MD PED

Item # 106

Item Description: HP laptop computer

Damage Description

The screen is cracked in two places. Shipper claims damage was noticed after move. He also showed slight damage to a key on the keyboard that he said was pre-existing. The screen is not useable. HP Mod. #CNF8094Q9T.

Est. Replacement Cost

\$ 900.00

Est. Repair Cost

N/A



I = Inspected
 NP = Not Present

NI = Not Inspected

MD = Moving Damage
 PED = Pre Existing Damage

I NI NP

MD PED

Item # **310**

Item Description: "Schecter" Electric Guitar

Damage Description


Shipper said the guitar was taken out of the case by movers and put back into the case backward. When the lid was closed the guitar neck was cracked at the joint to the guitar body. The neck is cracked and out of alignment at the joint to the base. Possible repair by guitar shop or factory. Instrument cannot be used now.

Est. Replacement Cost

\$ 600.00

Est. Repair Cost

N/A



I NI NP

MD PED

Item #

Item Description:

Damage Description

[Empty text box for damage description]

Est. Replacement Cost

\$ -

Est. Repair Cost

\$ -



furniture works



Inspection Report Summary

To:
Your Moving Company
1234 Moving Way
Anytown, State 98765
Attn: Company Rep
inspections@movingcompay.biz
Phone: (800) 123-4567 Ex. 123

Re:
Mr. A. Shipper
4321 Broken Dr.
Corpus Christi, TX 78413
(361) 723-0196
-
-

Shippers #: 1234567
Date Received: Feb. 12, 2010
Date Prepared: Feb. 23, 2010

Item #	Item Description	Estimated Replace Cost	Estimated Repair Cost
307	Floor lamp	\$ 50.00	N/A
248	Coffee table	\$ 300.00	\$ 50.00
250	Decorative storage chest	\$ 80.00	\$ 45.00
106	HP laptop computer	\$ 900.00	N/A
310	"Schecter" Electric Guitar	\$ 600.00	N/A

4201 Belfast Drive * Corpus Christi, TX 78413
361.723.0196 * Fax: 361.814.2796
movingclames@ccfurnitureworks.com